



1. 固定型不附外部控制線，部分線有拉到內部端子台，部分線需接到內部的設備上。
2. 馬達為AC/DC 110V，投入及跳脫線圈為DC 110V，由CTD供電。
3. SP1、SP2為壓力接點，LF1只附SP1，LF2/LF3附SP1及SP2。
SF1需25kA才能指定SP1，SP2無法供應。

| | | | |
|--|-------------------|--|--------------------|
| | Scale: DRAWING | Tolerancing Standard : SCALE | Units of measure : |
| | | PRESSURE SWITCH 2 TRESHOLD RI DIAGRAM SCHEMA RI PRESSDSTAT 2 SEUILS | |
| Number: | | 88946202 | Revision: 08 |
| <small>The information is highly confidential and is the exclusive property of Schneider Electric. Copyright reserved. This drawing must not be disclosed or reproduced in any way without permission from the owners in writing. The design must be returned to the owners when the purpose has ceased.</small> | | State: | Sheet: 1/2 |